

092305

1992 U.S. PTO

1/12





FIG. 1

Replacement Sheet

BEST AVAILABLE COPY

4/12




1 μ m

FIG. 4

Replacement Sheet

BEST AVAILABLE COPY

5/12



0.2 μm

FIG. 5

Replacement Sheet

BEST AVAILABLE COPY

6/12




FIG. 6

7/12




FIG. 7

Replacement Sheet

BEST AVAILABLE COPY

8/12




FIG. 8

Replacement Sheet

BEST AVAILABLE COPY

9/12




FIG. 9

Replacement Sheet

BEST AVAILABLE COPY

10/12




FIG. 10

Replacement Sheet

BEST AVAILABLE COPY

2/12




FIG. 2

3/12




FIG. 3

11/12




FIG. 11

12/12




FIG. 12